

Air Monitoring in the Rubber and Plastics Industries

B.G. Willoughby

rapra
TECHNOLOGY

Contents

1	What to Look for – What's There at the Start	1
1.1	Risk Assessment	1
1.2	Hazards from Ingredients	3
1.2.1	Accelerators and Activators	5
1.2.2	Antioxidants and Antiozonants	7
1.2.3	Blowing Agents	8
1.2.4	Colourants	9
1.2.5	Crosslinking Agents	10
1.2.6	Fillers	11
1.2.7	Flame Retardants	13
1.2.8	Heat Stabilisers	14
1.2.9	Monomers	14
1.2.10	Plasticisers	16
1.2.11	Retarders	17
1.2.12	Solvents	18
1.3	Likelihood of Exposure	20
1.3.1	Dusts (Airborne Particulates)	20
1.3.2	What is Dust?	20
1.3.3	How Does Dust Originate?	22
1.3.4	Airborne Vapours	23
1.3.5	Vapour Generation from Liquids	23
2	What to Look for – What's Created During Processing	31
2.1	Thermal Breakdown	32
2.1.1	Thermal Degradation of Polymers	32
2.1.2	Thermal Decomposition of Peroxides	33

2.1.3	Thermal Decomposition of Blowing Agents	36
2.1.4	Thermal Decomposition of Flame Retardants	36
2.2	Thermo-Oxidative Breakdown	36
2.2.1	Thermo-Oxidative Degradation of Polymers	36
2.2.2	Side-Chain Oxidation of Organo-Nitrogen Compounds	38
2.3	Crosslinking of Rubbers – Vulcanisation	39
2.3.1	Peroxide Crosslinking	39
2.3.2	Sulfur Crosslinking	39
2.3.3	Amines and Delayed Action Cures	41
2.3.4	Nitrosamines	43
2.4	Hazards from Volatile By-Products	46
2.4.1	Aldehydes	46
2.4.2	Aliphatic Amines	46
2.4.3	Ammonia, CAS: 7664-41-7	47
2.4.4	Aniline, CAS: 626-38-0	47
2.4.5	Benzene, CAS: 71-43-2	47
2.4.6	Biphenyl, CAS: 92-52-4	47
2.4.7	<i>tert</i> -Butanol (2-methylpropan-2-ol), CAS: 75-65-0	47
2.4.8	Carbon Disulfide, CAS: 75-15-0	47
2.4.9	Carbon Monoxide, CAS: 630-08-0	48
2.4.10	Chlorobenzene, CAS: 108-90-7	48
2.4.11	Hydrogen Halides	48
2.4.12	Ketones	48
2.4.13	α -Methylstyrene (2-phenylpropene), CAS: 98-83-9	49
2.4.14	<i>N</i> -Nitrosamines	49
2.4.15	Ozone, CAS: 10028-15-6	49
2.4.16	2,2',4,4'-Tetrachlorobiphenyl, CAS: 2437-79-8	50
2.4.17	Tetramethylsuccinonitrile, CAS: 3333-52-6	50
2.5	Likelihood of Exposure	51
2.5.1	Catalytic Effects	52

2.5.2 Residence Times	54
3 Air Monitoring Strategies	59
3.1 Concentration Profiling and Leak Detection	59
3.2 Personal Exposure Monitoring	61
3.3 Compliance with Legislation.....	62
3.4 Monitoring the Performance of Engineering Controls	63
3.4.1 Capture Efficiency	63
3.4.2 Transport Efficiency	65
3.4.3 Static Pressure	65
3.4.4 Velocity Pressure	65
3.4.5 Total Air Flow – Determination of Mean Velocity within a Duct	67
3.4.6 Volume Air Flow from Mean Velocity	72
4 Indirect Methods – Trapping Species from Air	75
4.1 Types of Airborne Pollutant	75
4.2 Whole Air Samples – Grab Sampling	76
4.3 Total Particulates Trapping	77
4.3.1 Inertia Trapping	77
4.3.2 Flow Rate Considerations	78
4.3.3 Filter Types	79
4.3.4 Handling Fibrous Filters	82
4.4 Sampling for Total Inhalable Particulates	82
4.5 Sampling for Respirable Particulates	84
4.6 Sampling in Ducts and Stacks – Isokinetic Sampling	86
4.7 Static Samplers	88
4.8 Gas and Vapour Trapping	88
4.8.1 Adsorption Trapping	89

Air Monitoring in the Rubber and Plastics Industries

4.8.2	Absorption Trapping	97
4.9	Portable Battery Pumps	104
4.9.1	Flow Rate Adjustment	110
4.9.2	Setting the Flow Rate	111
4.9.3	Battery Characteristics	112
4.10	Sampling and Sampling Records	113
4.10.1	Sampling Records	114
4.10.2	Field and Media Blanks	116
4.10.3	Sample Transfer and Storage.....	117
5	Indirect Methods – Laboratory Analysis	119
5.1	Overview of Chromatographic Techniques	120
5.1.1	Principles of Chromatography	120
5.1.2	Component Identification	123
5.1.3	Quantification	123
5.2	Gas Chromatography (GC).....	124
5.2.1	The Basics	125
5.2.2	GC Carrier Gas	126
5.2.3	Sample Introduction for GC – Liquid Samples.....	127
5.2.4	Split Injection for Capillary GC	128
5.2.5	Splitless Injection for Capillary GC.....	129
5.2.6	Cool-on-Column Injection	130
5.2.7	Sample Introduction for GC – Gaseous Samples	131
5.2.8	Columns and Ovens.....	132
5.2.9	Support Phases	133
5.2.10	Stationary Phases	134
5.2.11	Detectors	137
5.2.12	Instrumental Conditions	143
5.3	High Performance Liquid Chromatography (HPLC)	145
5.3.1	The Basics	145

5.3.2	Gradient Elution	146
5.3.3	Column Packing Material	146
5.3.4	Choice of Mobile Phase	147
5.3.5	Detectors	147
5.3.6	Sample Introduction	149
5.3.7	Instrumental Conditions	149
5.4	Ion Chromatography	150
5.5	Overview of Spectroscopic Techniques	151
5.5.1	Mechanics of Measurement	152
5.6	Flame Emission Spectroscopy (FES)	154
5.7	Atomic Absorption Spectroscopy (AA)	155
5.8	Inductively-Coupled Plasma Emission Spectroscopy (ICP)	156
5.9	Ultraviolet Spectroscopy	157
5.9.1	UV Fluorescence	159
5.10	X-Ray Fluorescence Spectroscopy (XRF)	160
5.11	X-Ray Diffraction (XRD)	161
5.12	Overview of Gravimetric Analysis	161
5.12.1	The Balance	162
5.12.2	Analytical Sensitivity	163
5.12.3	Cyclohexane Extraction	164
6	Indirect Methods – Data Analysis	165
6.1	Data Available	165
6.1.1	Pumped Sampling	165
6.1.2	Diffusion Sampling	166
6.1.3	Laboratory Analysis	167
6.2	Calculation of an Airborne Concentration	167
6.2.1	Units of Concentration – mg/m ³ and ppm	168

6.2.2	Use of ppm in Diffusive Sample Uptake Rates	170
6.2.3	Isocyanate Concentrations	170
6.3	Desorption Efficiency	171
6.4	Exposure Limits	172
6.4.1	UK Limits	173
6.4.2	US Limits	175
6.4.3	German Limits	176
6.4.4	Rubber Process Dust and Rubber Fume – UK Limits	177
6.4.5	N-Nitrosamines – German Limits	179
6.5	Time-Weighted Average (TWA) Exposures	179
6.5.1	Sampling Only During Working Periods	180
6.5.2	Sampling During Both Working Periods and Breaks	181
6.5.3	Assumptions	182
6.6	Exposure Records	183
6.7	Emission Limits	183
6.7.1	UK Legislation	185
6.7.2	US Legislation	186
7	Direct Methods	187
7.1	Colorimetric Methods	188
7.1.1	Detector Tubes: Short-Term Measurements	188
7.1.2	Detector Tubes: Long-Term Measurements	193
7.1.3	Colorimetric Filters and Badge Samplers	195
7.1.4	Paper Tape Monitors	195
7.2	Beam Attenuation or Deflection Devices	197
7.2.1	Infrared Absorbance (IR)	197
7.2.2	Ultraviolet and Visible Absorbance (UV-VIS)	201
7.2.3	Beta-Ray Attenuation	201
7.2.4	Light Attenuating Photometers	202
7.2.5	Light Scattering	202

7.3 Ionisation and Luminescent Detectors	204
7.3.1 Flame Ionisation Detectors (FID)	204
7.3.2 Photo-Ionisation Detectors (PID)	206
7.3.3 Chemiluminescent Detectors	209
Abbreviations and Acronyms	211
Appendix I	
Units and Conversions	217
Appendix II	
Methods for Determination of Hazardous Substances (MDHS), UK Health and Safety Executive.....	219
Appendix III	
NIOSH and OSHA Monitoring Methods - Representative Examples	227
Appendix IV	
Promulgated Test Methods from the US Environmental Protection Agency - Representative Examples	231
CAS Number Index	233
Subject Index	235