

Atlas of Wheel and Rail Defects

April 2004



UNION INTERNATIONALE DES CHEMINS DE FER
INTERNATIONALER EISENBAHNVERBAND
INTERNATIONAL UNION OF RAILWAYS

Table of Contents

Introduction.....	3
1. Defects Caused by Heat Generation from Sliding or Spinning	
WHEELS	
1.1W Spalls.....	4
1.2W Built Up Treads.....	6
RAILS	
1.1R Engine Burns.....	7
2. Fatigue Defects Originated Below the Surface	
Wheels	
2.1W Plate Failures.....	8
2.2W Shattered Rim Defects	
Deep Shelling	
Spread Rims.....	9
2.3W Flange Failures.....	10
2.4W Vertical Split Rim Failures.....	11
2.5W Tire Failures.....	12
RAILS	
2.1R Tache Ovale	
Kidney Failure	
Transverse Fissure.....	13
2.2R Horizontal Split Head.....	14
2.3R Horizontal Cracking with Transverse Cracking in Rail Head	
Compound Fissure.....	15
3. Defects Initiated from Surface or Near Surface_Fatigue	
WHEELS	
3.1W Thermal Cracks.....	16
3.2W Shelling.....	18
3.3W Tread Checks.....	21
RAILS	
3.1R Shelling.....	24
3.2R Rail Head Spalling.....	25
3.3R Squats.....	26
3.4R Transverse Defect Originating from Gage Face Deformation	
Detail Fracture from Shell	
Transverse Defect from Head Checking.....	28
4. Defects Initiated by Wear or Improperly Steering Bogies	
WHEELS	
4.1W Spread Rims.....	29
4.2W Hollow Tread and False Flange.....	30
4.3W Thin Flange.....	31
4.4W Rolled Over Tread.....	32

RAILS

4.1R Rail Gage Face Wear.....33
4.2R Crushed Head.....34
4.3R Alternating Side Wear.....35

5. Defects that Cause or Result from Impacts

WHEELS

5.1W Slid Flats.....36
5.2W Out-of Round Wheels (Type A – Tread Defect Initiated).....36
5.3W Out-of Round Wheels (Type B – Poygonization).....37
5.4W Dented Flange.....38

RAIL

5.1R Long Wave Length Corrugations.....39
5.2R Short Pitch Corrugations
 Rutting.....41
5.3R Weld Batter
 Dipped Joints.....43
5.4R Special Track Work Flange Damage.....44